

# ◀ HEALTH & SAFETY ALERT ▶




## TC125 – E-Tunnelling Machine

All Contractors should be aware that the following information provided within the TC-125TE Operating Instructions Manual is incorrect. This has been confirmed by TEREX and they are amending there manual.

The wording within bullet point 3 of section 7.2 states: “Turn the upper carriage so that the working direction is opposite to the dozer blade in the “straightaway” position.

The above statement is incorrect and those planning lifting operations for this machine should refer to FIG.32 (page 59 within the manual) which depicts the upper carriage in the correct position with the working direction over the dozer blade (shown below).

**FIG32**



Please warn your teams of the error in the manual until TEREX communicate their amendment.