

◀ HEALTH & SAFETY ALERT ▶



Whip Arrestors

There have been recent incidents where operatives have been struck by pressurised hoses.

In several of these a common factor has been the lack of whip arrestors see (Picture A).

All sites are reminded of the importance of fitting whip arrestors (see Picture B) particularly at extension points.

Picture A



Picture B

